NO.NC/QC/YD/2019-20/PH1 Date: 16-12-2019

To,
The Executive Engineer,
Dasarahalli Division
Bangalore.

"PMC CERTIFICATE AND INSPECTION REPORT"

Dear Sir,

Subject: Regarding Inspection Report for the below mentioned work.

Name of Work : Filling of pot holes Main & Cross roads in Dasarahalli Ward No.15

Item No	Description of work	Unit	Qty
1	Providing, laying, spreading and compacting cushed stone aggregates of granite / trap / basalt to wet mix macadam specifications including pre mixing the material with water at OMC in mechanical mix plant carriage of mixed	Cum	406.80
2	Filling Pot-holes and Patch Repairs with Bituminous Concrete, 40 mmKSRRB M3000-5. Removal of all failed material, trimming of completed excavation to provide firm vertical faces, cleaning of surface, applying tack coat on the sides	Cum	78.51

With respect to the above subject & name of the work, we have inspected the work and the Quantity and Quality of above mentioned items of the work was found to be completed satisfactorily for the 1st and Final bill

Thanking you,

With Regards,

For Newzen Consultants Bangalore

Scanned with CamScanner